

KOOTENAI DEVELOPMENT IMPOUNDMENT DAM SEPTEMBER 2011 ROUTINE OWNERS INSPECTION

Prepared for: The Remedium Group

Prepared by: Kurt Hafferman, P.E.

BILLMAYER & HAFFERMAN INC.

2191 3rd Avenue East Kalispell, Montana 59901

Inspection **D**ate: **S**eptember 29th, 2011 Report **D**ate: January 12th, 2**0**11



INSPECTION DATE:

Septe**m**ber 29th, 2**011**

REFERENCE:

SEPTEMBER 2011 ROUNTINE OWNERS INSPECTION

1.0 OBJECTIVES

The end of September 2011 routine owner's inspection was conducted on Thursday, September 29th, 2011. Personnel included Kurt Hafferman, P.E. and Dan Nelson from BHI and Jeremy Peterson from Chapman Construction.

The inspection was conducted as a routine owner's inspection. Project tasks to be completed included:

- 1. Safety meeting with Chapman and BHI
- 2. Check LRC-06 flows
- 3. Check Carney Creek and Lower Rainy Creek flows
- 4. Check Upper Rainy Creek and Fleetwood Creek inflows
- 5. Investigate upper Fleetwood Creek Pond
- 6. Read reservoir level
- 7. Record piezometer readings
- 8. Inspect the embankment dam
- 9. Inspect principal spillway
- 10.Inspect outside and inside of drains
- 11.Read flumes and weirs below the drain outlets
- 12. Read staff gauges in all streams above and below drain outlet channel
- 13. Download transducer data and reset transducers
- 14.Decontaminate and depart site

2.0 RESULTS

BHI met with Chapman Construction at 9:30 a.m. and the routine owner's inspection began at 9:45 a.m. and was completed at 1:30 p.m. The weather was clear, with calm winds. The temperature ranged between 40°F and 60°F. There were no weather impediments that affected the inspection. Copies of photographs from the date of the inspection are included in Appendix 1.

Copies of the Routine Owners Inspection Report as completed after the inspection and copies of the field notes are provided in Appendix 2. The following are the results of each of the thirteen (13) tasks described above;

1. Safety Meeting: Jeremy Peterson has been assigned as the health and safety officer and is responsible for equipment condition, decontamination procedures and over-all KDID site safety. The safety meeting with Chapman Construction included discussions of the work tasks and procedures for the day, equipment safety and operation, emergency procedures, truck traffic onsite and overall job site safety. Environmental Restoration (ER) continues operations at the amphitheatre and has staged decontamination equipment onsite. Equipment was checked, no issues were found and all personnel were equipped and prepared for the site conditions. Standard equipment used included: double Tyvek suits, rubber booties, double vinyl gloves and North® full face mask. Booties were taped at the top and Tyvek suits are taped at the zipper on the outer suit.

- 2. The LRC-06 flume was checked at the end of the inspection. The flume was clean and clear and a gauge reading was taken and recorded.
- Carney Creek and Lower Rainy Creek Flows: Flumes CC-02 and LRC-02
 respectively were read. Flumes were clear and gauge readings were taken and
 recorded, gauge readings are as follows;
 - a) The CC-02 Flume was read and the gauge height was recorded at 0.15 ft.
 - b) The LRC-02 Flume was read and the gauge height was recorded at 0.44 ft.
- 4. The Upper Rainy Creek and Fleetwood Creek flumes were read.
 - a) The URC-02 Flume was read and the gauge height was recorded at 0.38 feet.
 - b) The Fleetwood Creek flume was read and the gauge height was recorded at 0.18 feet.
- 5. The pond above the Fleetwood Creek flume was visited to determine if flows above the pond were greater than flows below the pond.
- 6. The reservoir level has continued to decline. The gauge reading on the staff gauge in the reservoir was recorded at 0.77 feet.
- 7. All piezometer's were read and recorded and levels are continuing to decline. An update of the piezometer plots is included in Appendix 3.
- 8. No bulges, erosion or other anomalies and/or changes were noted to the embankment from the upstream face to the toe.
- 9. The spillway was not running and the entrance channel was dry.
- 10. Drains were inspected and the flows in the drains and stream channel below the drains were measured and recorded. Water is still flowing in drain 2 with no detectable change in the rate of flow. Drain flows were all recorded as clear and steady.
- 11. All weirs and drains were read and recorded, no anomalies were noted. Results are shown in Table 1 below.
- 12. Gauge height readings from the flumes and weirs in streams and below the toe drains were taken. Results are summarized in Table 1 below.
- 13. All four (4) transducers onsite were downloaded during the inspection and the transducers were reset. Data will be processed and reviewed. As the Spillway is no longer running that transducer has been removed and will be placed in piezometer A8.
- 14. Initial personnel and equipment decontamination was conducted at the contamination reduction site with ER pressure washing equipment. Final removal of the inner Tyvek suit and the mask took place at the support trailer.

The readings from all the streams flowing into and out off the site, including the flumes, weirs and reservoir levels are compiled in Table 1 below. Table 2 shows the net difference between inflows and outflows on the day of the inspection.

Table 1: Flow Measurement Results

Station	GH Reading (ft.)GH Reading iast Month	GH Reading (ft.)GH Reading this Month	GH Reading Difference from last month.	Flow (gpm)/VOL (AF) last Month	Flow (gpm)/ VOL (AF) This Month	Flow/VOL Difference from last month.	Temp °F
URC02	0.49	0.38	-0.11	219 gpm	131 gpm	-88.0 gpm	45° F
Fleetwoo d Creek	0.20	0.18	-0.02	25.6 gpm	20.7 gpm	-4.9 gpm	43°F
Reservoir	1.37	0.77	-0.60	33.21 AF	22.60 AF	-10.61 AF	49°F
F 1-2-3-4	0.25	0.15	-0.10	40.4 gpm	14.5 gpm	-25.9 gpm	
W 5	0.146	0.125	-0.021	9.46 gpm	6.43 gpm	-3.03 gpm	
D 6	0.849	0.948	-0.099	294 gpm	102 gpm	-192 gpm	
F 7-8	0.10	0.11	+0.01	4.53 gpm	5.48 gpm	+0.95 gpm	
W 12	0.333	0.26	-0.073	73.1 gpm	39.6 gpm	-33.5 gpm	
F -Seep	0.21	0.15	-0.06	28.3 gpm	22.7 gpm	-5.6 gpm	
LRC01	0.30	0.22	-0.08	684 gpm	450 gpm	-234 gpm	
CC02	0.14	0.15	+0.01	67.32 gpm	76.3 gpm	+8.97 gpm	42°F
LRC02	0.58	0.44	-0.14	783 gpm	497 gpm	-286 gpm	45°F
LRC06	0.65	0.55	-0.10	909 gpm	702 gpm	-207 gpm	
Spillway	0.00	0.00	0.00	0 gpm	0 gpm	O gpm	

Table 2: Total Flows

Total Flows	
Inflows Above Reservoir at URC02 and Fleetwood Creek	152 gpm
Outflow Below Reservoir above CC02	450 gpm
Difference (Out flows greater than inflows)	+298 gpm

3.0 DISCUSSION

3.1 Weather Updates

The precipitation in this area as of **S**eptember 29th, 2011 is reported as 133% of normal at the Banfleld Mountain recording site which is located just northwest of the project, indicating the water year, beginning October 1, 2010, in the vicinity of the project is still above normal. The entire Kootenai basin shows precipitation levels at 120% of normal.

The temperatures in the past month have ranged from a low of 32°F to a high of 91°F and there has been 1.0 inches of precipitation since the August inspection.

The water year ended on **S**eptember 30th, the day after the inspection with a total of 51.3 inches of precipitation at the Banfleld Mountain recording site and 133% of normal precipitation. The 2010-2011 water year was the wettest year since 2008 and is the wettest year in the last 14 years (since 1997). Normal precipitation is estimated at 38.5 inches in this area based on NRC**S** records from 1971-2000.

3.2 Site Access

Jeremy Peterson was the onsite health and safety, equipment and personnel safety officer and arranged for site access prior to the site visit. Jeremy was the means of transportation while Mr. Hafferman and Mr. Nelson carried out the inspection. ER continues operations on the site and the inspection crew checked in at the entrance shack per EPA requirements. As required for safety, large trucks were followed on haul roads.

Access to the site was obtained with the Ranger ATV. The ATV sustained a flat tire midway through the inspection. It was decided that the remainder of the inspection, from the crest to the toe of the dam would be completed by Kurt and Dan on foot and they would walk to the decontamination area while Jeremy took the ATV to the decontamination area and retrieved the truck. Both Kurt and Dan have maintained a healthily life style and have recently committed to keeping in shape and work out weekly; mainly because of the physical requirements of this job and in particular in the winter. This mishap is a prime example of why BHI and Chapman maintain a regular safety program that includes worker health. This is a remote location and may require that workers be able to walk, sometimes in the snow, from the top of the mine site to Highway 2, a distance of 7.5 miles. A spare tire will be recommended to Chapman in the future as standard equipment when using the ATV.

3.3 Fleetwood Creek Pond and Upper Reservoir

BHI has noted that groundwater flows from KDID drains are higher than surface water volumes and BHI is looking for sources of groundwater infiltration at the valley margins, and in particular, at inflection points in the local topography. As part of this inspection, BHI visited the small pond above the Fleetwood Creek flume to check for diminishing flows that would indicate water was infiltrating into the ground before it reached the reservoir.

The site inspection showed that Fleetwood Creek has been re-routed to bypass the pond and water from the creek appears to only flow toward the pond under high flow conditions; therefore upstream and downstream flows were unchanged and the pond is not a source of groundwater infiltration, at least at low flows. It appears that the pond acts as a low spot collecting excess stream flow, rain runoff and snowmelt. The pond shows evidence of high and low water so the water must infiltrate into the ground or evaporate in order to leave the pond but it is not a definitive source of water infiltration.

Fleetwood Creek was followed until it enters Rainy Creek to determine if there was a section of stream where the stream flowed underground. What was found was that the stream enters the upper reservoir and flows, without significant loss of flows. Therefore all surface water from Fleetwood Creek appears to enter the upper reservoir.


3.4 Surface Water Flows

Inflows into the reservoir show a continued decline through the summer season in conjunction with drying conditions. The inflow from Upper Rainy Creek was recorded at 131 gpm and Fleetwood Creek was recorded at 21 gpm for a total reservoir inflow

of 152 gpm on September 29th. Inflows show a 38% reduction over the flows measured in August. Inflow volume over the past month was measured at 18.8 AF and outflow volume at LRC-01 measured 39.6 AF; 21 AF more water flowed out of the drains than flowed into the reservoir.

The transducer data downloaded this month did not match up to previous month's data over the season cycle and required values to be averaged to make the data fit. No sudden data shift or data reading error could be found to adjust the data and it is assumed at this time that a new calibration on the transducers may be needed as the reading shift appears to be gradual. Therefore volume values used this month are informational only and no concise conclusions can or should be drawn from them at this point.


Reservoir outflows into Lower Rainy Creek have gone from 684 gpm in August to 450 gpm during this inspection, a drop of 34%. The spillway has not been noted as flowing Since July 28th, so all flows are routing through the toe drains or the foundation gravels as they move through the impoundment area. Figure 1 below compares surface water inflows and outflows since June 23rd.



In the graph above, we can see that outflows have been consistently higher than inflows. Inflows include Upper Rainy Creek and calculated Fleetwood Creek flows and outflows include toe drain and spillway flow below the toe of the dam. Of particular interest are the continued matching flow patterns above and below the impoundment. As previously mentioned, there is not a calculatable lag time between

inflow and outflow responses with the current 30 minute interval transducer readings.

This correlation is unexpected and will be monitored more closely in the coming months. To calculate a lag time, the transducers will be set to record at faster intervals during the next inspection to see if a delay in flow changes can be measured. Figure 2 below shows the inflows and outflows along with the flows recorded at LRC-02 below the mill pond.



As previously discussed, the graph above is the same as Figure 1 except it includes the flow data obtained from MWH Global for the LRC-02 flume which sits below the mill pond. LRC-02 is measuring the same water as LRC-01 except for the addition of groundwater discharges and Carney Creek, which was removed in the graph above.

As can be seen, both the outflows at LRC-01 and LRC-02 are consistently higher that the inflows at URC-02, providing a second means to verify that outflow volumes are higher than stream inflows.

3.5 Reservoir

As with surface water flows, the reservoir level has continued to decline over the past month and was reading 0.77 feet and the water level was approximately 400 feet from the upstream crest of the dam on the date of this inspection. The reservoir is

still approximately 0.7 feet higher than normal for this time of year. Figure 3 below shows the updated reservoir level vs. piezometers.




Figure 3: Reservoir vs. Piezometers

As shown above all piezometer levels are continuing to decline with falling reservoir and inflow levels; as is typical for this time of year. The transition to seasonally low levels continues to be near 1 month behind typical values measured and recorded onsite.

3.6 Spillway

The principal spillway was not been visually recorded as running since July 28th and ran for a total of 108 days this spring. Calculated flows estimate that from May 25th to July 28th, a total of 236AF of water went over the spillway for an average flow of 500 gpm over the spillway this spring. To BHI knowledge, this is the longest the spillway has ever run.

3.7 Drains and Drain Flows

Toe drains continue to show declining flows through and under the impoundment. All flows were noted as clear and steady with no visible transport of sediment in the drain water. Root wads were noted in a few of the drains, were cleaned out on site, and do not appear to pose an immediate threat to drain flows.

Flows in <u>drain 1</u> have ceased for the season. <u>Drain 2</u> is still running with a decline in flows over last month to less than 1 gpm. It is feasible that drain 2 will cease flows by next month's inspection. Of significance is the black globs of sediment that has been noted at the outlet of the drain and was visibly running in the pipe on August 23rd when a video inspection was carried out on the site. While no continued visual movement has occurred, we continue to see the same deposits at the end of the pipe that indicate this transport may still be intermittently occurring.

<u>Drains 3 and 4</u> decreased flow again this month. Flows appear to be normal for the time of year and no new material transport has been noted.

<u>Drain 5</u> is still sustaining higher flows than normal at this time and, based on data this year, has possibly increased capacity. Drain 5 has also shown signs of sediment transport and the area upstream of the weir 5 has fliled in. It may be that flushing the pipe of sediment has resulted in an increase in flow capacity in drain 5. While drain 5 flows are small in comparison to other drains, its reaction to this years high flow has been interesting and will be monitored.


<u>Drain 6</u> was recorded at 102 gpm down from 294 gpm on August 25th, a reduction of 65%. This flow is normal for the time of year but is low when compared to the flows occurring at other drains in the system. Drain 6 flows typically account for 67.5% of all surface water inflows and this month only accounted for 23% of the total flow. It may be that drain 6 had the opposite affect as drain 5; the higher flows may have reduced capacity. This trend will be closely monitored.

BHI has recently had conversations with two former W.R. Grace mine personnel and Libby residents, Dan Youso and Mike Munro in regards to the drain 6 steel pipe. Kurt went to high school with both Mike and Dan and used the personal connection too attempt to get a reliable interview from people that were actually on site during the original KDID construction. Both Mike and Dan stated that they worked on the original construction of the embankment starter dam in the mid 1970's. Both Dan and Mike were interviewed independently and both stated that they were young at the time and their recollection is vague but to the best of their knowledge, the pipe that feeds drain 6 runs well out into the reservoir and may even reach to the upper impoundment. Mike remembered that he had spent a considerable amount of time bedding a large steel pipe. Dan's stated that he mainly pushed dirt toward the track hoes bedding the pipe and he felt that the work he did was mainly in the starter dam. Neither remembered seeing gravel cross drains and neither recognized the Phase 1 plan view or cross section. This is typical of research that BHI has conducted; the people have either passed away, have moved and can't be reached or just do not remember as it was over 30 years ago. BHI has speculated in recent months that lacking any other persons, attempting to find persons that can describe the concise locations well enough that it could be documented on a plan set is a futile effort.

Flow has ceased in <u>drain 7</u> but seepage below the pipe continues and appears as clear and steady. <u>Drain 8</u> also is flowing clear and steady. The gauge height on the flume 7-8 showed a surprising 0.01 foot increase over last month when most drain flows on the project show a decline in flows. Drain 8 shows some sign of fine grained black sediment transport which shows up in flume 7-8. The flume was cleaned and will be monitored for sediment transport next month.

<u>Drain 9</u> shows lower flows than last month and correlates to the decreasing inflows on the project. A root wad was pulled from the pipe and is shown in figure 4 below. No sediment was noted as being trapped behind the root wad and no change in flow was noted.

Figure 4: Root Wad in Drain 9




<u>Drain 10 and 11</u> are at normal flows for this time of year and no anomalies were noted.

<u>Drain 12</u> has also reduced flows and a small root wad was removed during the inspection. Review of past data shows that drain 12 flows are nearly double those recorded last year. Monthly inspections are still indicating some gravel and fine grained sediment material is being transported but not in the quantities noted this spring. Review of 2010 video footage showed that drain 12 was previously videoed to end in a pile of loose rock and sediment that would be subject to transport if water reached the level of the end of the drain. We therefore suspect that the terminal end of the pipe is the source for the material transport noted in drain 12 this year.

3.8 Piezometers

Piezometer readings have continued their decline and continue to stabilize near normal levels. Based on precipitation observations, the water and piezometer levels experienced this year should be expected at a nearly annual basis when normal moisture levels are present. These conditions were last encountered in 2008 when near normal precipitation levels were recorded at the Banfield Mountain site. However the phreatic water surface reaction seen this year was more extreme than in 2008. It is not known if the rapid rise and fall is linked to the higher flows or the changes noted in the drain system; i.e. gravel and sediment transport and changes in drain 6 capacity. The piezometers are to continue to be monitored for any indication of changing conditions in the reservoir and or embankment itself.


The Piezometer P2 transducer was downloaded during this inspection along with the other transducers and plotted against the reservoir to check for adverse changes or correlations. Figure 5 below shows this graph.



The graph above shows the continued decline of piezometer P2 and the reservoir. P2 showed no abnormal spikes or changes and as shown above is nearing typical low phreatic water surface levels. The piezometer has risen and dropped over 40 feet since peak levels were measured on May 18th this spring.


The updated piezometer plots from 2002 to the date of this inspection are shown in Figure 6 below.





The graph above shows the highest recorded levels and well as the return to normalized levels and the annual cyclic changes that occur on the project. Figure 7 below shows the same piezometers, but over a shorter period of time.

Figure 7: Piezometer Elevations 2008-2011



The graph above represents data collected since BHI began onsite inspections. We can see that piezometer A8 is dropping slower than the other piezometers on the site and shows the higher than normal phreatic water surface at the toe of the dam. Water levels this year at A8 have fallen slower than past years and indicate the volume of groundwater still present and moving below the dam. Figure 8 below shows the flat sustained peak in piezometer A8 at the toe of the dam that is not typical.




Figure 8: Piezometer A8 and Toe of Embankment

4.0 HAZWOPER UPDATES

BHI continues to conduct safety meetings at the beginning of each inspection. All personnel have current certifications, equipment is maintained in good working condition and we have no personnel issues at this time.

The ATV and all equipment are washed with pressure washing equipment supplied by ER. Decontamination will be conducted with their equipment and water until operations are discontinued in the fall. The equipment decontamination was completed successfully without malfunction, outer Tyvek suits were removed at the contamination reduction area. Personnel then proceeded to the support trailer to complete the decontamination and depart.

5.0 CONCLUSION

No anomalies in the alignment of the dam were noted. No bulges, surface erosion or other physical sign of failure were noted on the site. The principal spillway and emergency spillways are clear with no obstructions and the concrete is in good to excellent condition.

Generally all flow and phreatic water surface readings recorded this month are lagging about 1 month behind, that is to say they are higher than normal levels, when compared to past readings on the site.

Outflows at the toe of the dam continue to be greater than inflows. Surface water inflows accounted for only 36% of the total outflows on the date of this inspection and were calculated from the data to be 47% of the outflow volume over the past month. This month surface water inflows totaled 18.8 AF while outflows totaled 39.6 AF. The reservoir level dropped roughly 10.6 AF therefore the net outflow was 10.2 AF more than surface water inflows. The average inflow into the impoundment was 121 gpm and the average outflow through the toe drains at LRC-01 was 256 gpm. The average flow attributed to reservoir level depletion over the last month was 69 gpm. Based on the above values groundwater flow rates over the past month accounted for 26% of the outflows and, as discussed above and in the July and August reports, indicates that groundwater flow into the drain system is a significant portion of the total outflow. It is noted that the contribution of groundwater is subsiding and the net difference between the two is getting smaller but there is still a net increase in the volume of flow at the toe of the dam.

Since transducer installation at URC-02 on June 23rd to the date of this inspection inflows have totaled 208 AF and outflows at LRC-01, including the measured spillway flows have totaled 454 AF. Reservoir volume drop over the same period was 41 AF. Therefore the net surface flow including reservoir level change is 249 AF and outflows at 454 AF were 1.82 times greater than surface water inflows. Therefore groundwater flows accounted for 45% of the total outflows through the drains over this monitoring season.

As discussed in previous reports, transducer data above and below the reservoir show that inflows and outflows are in some way immediately and directly connected, because there is no measurable lag time between upstream flow fluctuations and downstream flow fluctuations within the 30 minute transducer interval readings. The flumes are 4,500 feet apart, so for a fluctuation time less than 30 minutes the water flow rate is still calculated to be greater than 2.5 feet/second between the flumes. As previously stated, this flow rate is only capable in open channels, open pipes, and in very pervious and cavernous groundwater conditions and is not feasible as an infiltration rate through the tailings. BHI continues to suspect that there is an open pipe in the reservoir that is tying inflows to outflows.


RECOMMENDATIONS

No new recommendations at this time. Recommendations from past reports are included below.


- 1. <u>Investigate Pond Area:</u> The rapid draining of the pond west of the access road should be investigated to determine first, why it occurred and second, what the repercussions of this event have on the long-term stability of the dam. Questions to be answered during this investigation are; where the intake structure is for the previously discussed Phase 5 decant tower and is it affecting the pond elevation and are there other sources feeding the pond and how are they related to fluctuation in the reservoir level.
- 2. <u>Drain Flows and Piezometers:</u> Continued monitoring of all previously established monitoring devices throughout the site in order to identify relationships in water level fluctuation and their potential impact on the dam. Continue to monitor sediment transport below the drains that appear to be actively moving gravel and sediment.
- 3. <u>Investigate Groundwater</u>: The recent findings that show roughly 50% of drain flow is groundwater should be investigated. The characteristics of this groundwater aquifer below the dam and above it should be determined. This investigation would include a drilling program at the toe and crest of the dam as well as upstream of the impoundment to determine its limits and how it interacts with the dam and surface water flows. Cased holes should be left at select drilling locations to allow aquifer testing.
- 4. <u>Winter Decontamination:</u> It is recommended that with the upcoming cold weather that related personnel, equipment and decontamination protocol is established by BHI and Chapman Construction to provide documented and acceptable procedures for the different conditions and limitations encountered on the site. In addition it is recommended that all personnel that are to be on site during the winter are capable of sustained physical exertion for at least three hours and they are capable of self rescue at all times.

APPENDIX 1 SITE PHOTOGRAPHS





Carney Creek above Flume



CC-02 Inlet



CC-02 Gauge Height



CC-02 Outlet




CC-02 ISCO Reading



LRC-02



LRC-02 Inlet




LRC-02 Gauge Height






LRC-02 Outlet




LRC-02 ISCO Reading



Fleetwood Creek above Flume



Fleetwood Creek Flume




Fleetwood Creek Gauge Height



Culvert above pond - Old Fleetwood Creek Channel




Pond near Fleetwood Creek





Overlooking Reservoir













Reservoir towards Rainy Creek Inlet




Reservoir towards Mine






Reservoir towards Embankment Dam




Reservoir Gauge Height




Upstream Dam Crest to Right



Upstream Dam Crest to Left



Reservoir from Embankment Dam




Downstream Crest to Right




Downstream Crest to Left




Left Downstream Abutment




Right Downstream Abutment



Box Culvert Entrance




Inside Box Culvert



Trash Rack




Principal Spillway



Upper Lift Line on Downstream Face from Left



Drain 1



Inside Drain 1




Drain 2



Inside Drain 2



Drain 3




Inside Drain 3





Drain 4



Inside Drain 4




Channel below Drain 3





Flume Drains 1-4





Flume Drains 1-4 Gauge Height





Inside Drain 5





Drain 5 Weir



Drain 6








Drain 7 and 8



Seepage below Drain 7



Inside Drain 7



Drain 8




Inside Drain 8






Flume Drains 7-8



Flume Drains 7-8 Gauge Height



Lower Rainy Creek below Drain 6




Root wad pulled from Drain 9



Drain 9




Inside Drain 9



Drains 10 and 11




Drain 10




Inside Drain 10



Drain 11



Inside Drain 11




Channel below Drain 12




Drain 12 Weir



Drain 12




Inside Drain 12




Gravel at Drain 12 Outlet



LRC-01 Flume



LRC-01 Gauge Height




LRC-01 Outlet



F-Seep Flume


R.56.1 Monthly Dam Inspection September 2011



F-Seep Gauge Height



LRC-06 Inlet





LRC-06 Outlet

APPENDIX 2

PERIODIC INSPECTION REPORT & FIELD NOTES

INCIPAL I	NSPE	CTOR ON SITE: Kurt Hafferman, P.E.	OBSERVATION DATE (S)		2 9-S€	p-11			
		EL ON SITE: Dan Nelson from BHI and Jeremy apman Const.	WEATHER CONDITIONS	Clear, ~40-60°, Calm					
ervoir lev	el, me	ure flows, check URC02 and Fleetwood Creek, take easure piezometers, check drains, drain flow, gauge CC02, LRC02 and LRC06, Download transducers.	EQUIPMENT	Well probe, I	ong fiberglas: sc. field equip	s tape, camer).	'a,		
CTED		EMBANKME	NT	CHECK ACTION NEEDED					
AREA INSPECTED	TEW NO.	CONDITION	OBSER V ATION	ZONITOR	NVESTIGATE	REPAIR	отнек		
	1	GENERAL SURFACE CONDITION	Good, no change						
ļ		DISPLACEMENTS	None	Į					
1		EROSION CREST ALIGNMENT	None	ļ					
		WEEDS OR BRUSH	Good, no change No change						
ł		ANIMAL BURROWS	No change	 			 		
⊢ ⊦		EARTHEN EMERGENCY SPILLWAY	Good, no change	 			 		
CREST			Good, no Glange	 					
8	8 9	• • • • • • • • • • • • • • • • • • •		 					
	10	SLIDES, DISPLACEMENT OR BUDGES	None	 					
Ī		EROSION	None	 					
		WEEDS OR BRUSH	No change	 					
FACE		PIEZOMETER CASINGS	Good, no change						
š .[ABUTMENT CONTACTS	Good, no change						
Σ		ANIMALS BURROWS	No change						
Ā		DISTANCE TO WATER	~400 ft. resen/oir GH= 0.77 feet						
E.	17								
UPSTREAM	18			<u> </u>					
	19								
JITIONAL	COM	MENTS, REFER TO ITEM NO. IF APPLICABLE							

NCIPAL I	NSPE	CTOR ON SITE: Kurt Hafferman, P.E.	OBSERVATION DATE (S)		9/29	9/11	
		EL ON SITE: Dan Nelson from BHI and Jeremy pman Const.	WEATHER CONDITIONS	Clear, ~40	-60°, Calm		
ervoir lev	el, me	ure flows, check URC02 and Fleetwood Creek, take asure piezometers, check drains, drain flow, gauge C02 , LRC02 and LRC06, Download transducers.	EQUIPMENT	Well probe, i	long fiberglas Sc. field equit	s <i>ta</i> pe, camer).	a,
TED		DOWNSTREAM AND INSTR	_ c	HECK ACT	ION NEEDE	ĒD	
SLOPE AREA INSPECTED	TER NO.	CONDITION	OBSERVATION	MONITOR	NVESTIGATE	REPAIR	OTHER
ᇎ		GENERAL SURFACE CONDITION	Good no change	191			
9[DISPLACEMENTS	None				
		EROSION	None				
DOWNSTIREAM		LIFT ALIGNMENTS	Good				
9		WEEDS OR BRUSH	No change				
Ĕ[ANIMALS BURROWS	No change				
z [26	EARTHEN EMERGENCY SPILLWAY	Good, no change				
		SEEPAGE	None				
ă		ABUTMENT CONTACTS	Good, no change	-			
		PIEZOMETERS	Measured, see attached measurements	X			
[WEIRS	Gauges read, see attached	X			
<u>ج</u> [FLUMES	Gauges read, see attached	X			
ĔĹ		RESERVOIR LEVELS	GH = 0.77' Approx. 22.60 AF	X			<u> </u>
ΣL		RAINY CREEK INFLOW MEASUREMENTS @ URC02	GH= 0.38, 130.6 gpm	X			
E E		RAINY CREEK OUTFLOW BELOW DAM @ LRC01	GH= 0.22, 450 gpm	X			L
5		STREAM OUTFLOW BELOW MILL POND @LRC02	GH=0.44, 497 gpm	X			
ᇎ	36	STREAM OUTFLOW FROM CARNEY CREEK @CC02	GH=0.15, 76.29 gp m	X			
INSTRUMENTATION	37	STREAM OUTFLOW FROM RAINY CREEK @LRC06	GH=0.55, 702 gpm	X			L
		FLUME 1-2-3-4	GH=0.15, 14.5 gpm	X	L		<u></u>
DITIONAL	COM	MENTS REFER TO ITEM NO. IF APPLICABLE					

RINCIPALI	NSPE	CTOR ON SITE: Kurt Hafferman, P.E.	OBSERVATION DATE (S)		9/29	/11				
		EL ON SITE: Dan Nelson from BHI and Jeremy apman Const.	WEATHER CONDITIONS	Clear, ~40-60°, Calm						
eservoir lev	ei, me	ure ffows, check URC02 and Fleetwood Creek, take asure piezometers, check drains, drain flow, gauge CC02, LRC02 and LRC06, Download transducers.	EQUIPMENT	Well probe, long fiberglass tape, camera, flashlight,misc. field equip.						
E		INSTRUMENTATION (CONT.) AND DO	WNSTREAM TOE AREA	CHECK ACTION NEEDED						
AREA INSPECTED	TES NO.	CONDITION	OBSERVATION	MONITOR	NVESTIGATE	REPAIR	OTHER			
	39	FLUME 10-11-12	Removed, no longer used							
7		FLUME 7-8	GH=0.11, 5.48 gpm	Х						
INSTRUZENTATION (CONT.)		WEIR 5	GH= 0.125, 6.43 gpm	Х						
_ ₹		WEIR 12	GH=026, 39.57 gpm	Х						
		DRAIN 6	GH=0.948, 102.2 gpm	Х			ļ <u> </u>			
₩ 🤝		SPILLWAY FLOW	GH=0.00 - Not Running	Х						
INSTRU		F-Seep	GH=0.15, 22.7 gpm	X						
<u>∞</u> ∑		Drain 2	Water continuing to flow	X	X	 				
<u> </u>		Drain 1	No Flow	Х						
		ABUTMENTS	Good, no change	L			[
Ö		SEEPAGE NEAR TOE SEEPAGE DOWNSTREAM OF TOE, LEFT SIDE	Not noticed	X			 			
5		SEEPAGE IN STREAM OF TOE, LEFT SIDE	Not noticed Not noticed		X					
⊼ੁ		VEGETATION	Unchanged in last month	X						
图		CULVERT AT LOWER ROAD	Not monitored	 ^			 			
DOWNSTREAM TOE		SEEPAGE DOWNSTREAM OF TOE, RIGHT SIDE	Not noticed	<u> </u>						
<u>Ş</u> t	55			- ~						
2	56			 						
	COM	MENTS, REFER TO ITEM NO. IF APPLICABLE								

RINCIPAL II	VSPE	CTOR ON SITE: Kurt Hafferman, P.E.	OBSERVATION DATE (S)	9/29/11					
		EL ON SITE: Dan Nelson from BHI and Jeremy apman Const.	WEATHER CONDITIONS	Clear, ~40	-60°, Calm				
servoir leve light at LR(el, me	ure ffows, check URC02 and Fleetwood Creek, take easure piezometers, check drains, drain flow, gauge CC02, LRC02 and LRC06, Download transducers.	EQUIPMENT		ong fibergias sc. fiald equi		a ,		
		SPILLWAYS	3	C	HECK ACT	ION NEEDE	ĒD		
AREA INSPECTED	ITEM NO.	CONDITION	OBSERVATION	RONITOR	INVESTIGATE	REPAIR	отнек		
× 8	58	ENTRANCE CONDITION	No changes noted						
ĝ ≸[CENTERLINE CRACK FLOOR	No changes noted	X					
2 3		CENTERLINE CRACK CEILING	No changes noted	Х	X				
S E A		TRANSVERSE JOINTS	No change, same CaCo3 deposits						
크용삗		GENERAL CONCRETE	Good to excellent, no change						
		SEEPAGE OR WATER	None noted	X					
		OPEN CHANNEL CONCRETE	Good to excellent, no change						
절품필	65	OPEN CHANNEL JOINTS	Good to excellent, repairs made	X					
PRINCIPAL SPILLWAY (BOX CULVERT AND OPEN CHANNEL CHUTE SPILLWAY)		OPEN CHANNEL GENERAL	Good						
		JOINTS	Good						
		WALL CONCRETE	Visual from above, good						
5 × 1		FLOOR CONCRETE	Visual from above, good						
ا≷ اا		WALL TOPS	Good	 _					
출기		WEEDS ALONG WALLS	None noted	ļ					
돌림		STILLING BASIN RIPRAP	Good	<u> </u>		<u> </u>			
골 XIL	74	WEED AND BRUSH IN STILLING BASIN	No change	ļ	ļ				
25	75			 	ļ	ļ			
OPEN CHANNEL STEEP CHUTE SPILLWAY	76			 					
		MENTS, REFER TO ITEM NO. IF APPLICABLE		<u> </u>		L			

R <i>incip</i> al i	NSPE	CTOR ON SITE: Kurt Haflerman, P.E.	ENT DAM ROUTINE OWNERS INSPECTIO OBSERVATION DATE (S)		9/29	9/11		
		EL ON SITE: Dan Nelson from BHI and Jeremy apman Const.	WEATHER CONDITIONS	Clear, ~40	-60°, Calm			
eservoir lev	el, me	ure flows, check URC02 and Fleetwood Creek, take asure piezometers, check drains, drain flow, gauge CC02, LRC02 and LRC06, Download transducers.	EQ <i>UIP</i> MENT	Well probe, i flashlight;mi	iong fiberglas isc. field equip	s tape, camer o.	a,	
9		RESERVOIR AND UPSTREAM I	DRAINAGE BASIN	CHECK ACTION NEEDED				
AREA INSPECTED	ITE解 NO.	CONDITION	OBSERVATION	MONITOR	INVESTIGATE	REPAIR	ОТНЕК	
	77	LEFT SIDE (TAILINGS SLOPE)	Stable Stable					
[RIGHT SIDE	Stable					
Ĺ		RESERVOIR LEVEL	GH=0.77 ft.	X				
[WETLANDS	Good, no change					
€[UPPER POND	Full					
<u> </u>		DISTANCE FROM UPSTREAM SLOPE	~ 400 ft. and receeding	X				
RESERVOIR	83							
<u> </u>	84							
~	85							
7		PRECIPITATION WY 2010-20111 AS OF DATE OF INSP.	133% of normal at Banefield. Entire Basin at 120% of normal	х				
BASIN	87	RECENT RAINS	1.0 inches of precipitation in the last month.	х				
DRAINAGE		FIRE DANGER	Medium-High					
ĕ [CHANGES	None					
₹[VEGETATION	No change in past month					
Ӽ[RAINY CREEK DRAINAGE	Continued decline in flows					
M	92	FLEETWOOD CREEK DRAINAGE	Continued decline in flows					
UPSTREA	93	MINE SITE	ER continues opperations for the summer					
[S	94							
<u>-</u> -	95							


PR <i>incip</i> al i	NSPE	CTOR ON SITE: Kurt Hafferman, P.E.	OBSERVATION DATE (S)		9/29	9/11	
		EL ON SITE: Dan Nelson from BHI and Jeremy opman Const	WEATHER CONDITIONS	Clear, ~40)-00°, Calm		
reservoir lev	el, me	ure flows, check URC02 and Fleetwood Creek, take asure piezometers, check drains, drain flow, gauge C02, LRC02 and LRC06, Download transducers.	EQUIPMENT	Well probe, flashlight,m	iong fibergias isc. field equip	s tape, camer	A,
TED		EARTHEN SPILLWAY AND MILL	POND AND OTHER	C	HECK ACT	ION NEEDE	.D
AREA INSPECTED	ITEM NO.	CONDITION	OBSERVATION	SONITOR	NVESTIGATE	REPAIR	OTHER
>	96	LEFT SIDE NEXT TO CREST	Good, no change				
SPILLWAY		RIGHT SIDE	Good, no change				
31		RESERVOIR LEVEL	Normal				
<u>,</u>		RIPRAP	Good, no change				
		ROAD CONDITION DOWNSTREAM SLOPE	Good, no change				
모		TRASH RACK	Good, no change	X	 		
₽ŀ	103		No change in past month		ļ		
EARTHEN	104				 		
<u> </u>		CREST	Good				
}		UPSTREAM FACE	Good		<u> </u>		
ł		DOWNSTREAM FACE	Good				
ł		SPILLWAY FLOW	Flowing		 		
ام		RIPRAP IN SPILLWAY	Good, no change				
POND					 		
	110	ANIMALS ON EMBANKMENT	Not seen	X			
1		ANIMALS IN SPILLWAY	Not seen		T		
	112	RESERVOIR LEVEL	Normal	Х			
OTHER	112	Animals Monitoring	None noted during this visit	x			
		MENTS, REFER TO ITEM NO. IF APPLICABLE	None noted during this visit.	<u> </u>	<u> </u>	<u> </u>	

.

Kurtis M. Hafferman, P.E.	MT PE 10457	Date

Location	Date
Project / Client	


25



Loca	tion_									Da	ate				- `
Proj∈	ct/C	Client	·				<u> </u>				· · · · · · · · · · · · · · · · · · ·		٠,		-
1										·					- <u>:</u>
		L	66	6	Γ										ŀ
<u>. </u>	-	- 5	00	-	<u> </u>	_						<u> </u>	 		
	_	<u> </u>	<u> </u>	Gq	م	15		_			ļ		 		
		Ľ_								<u> </u>		ļ			ļ
) 6	ع ع	O											
		2-4	C	1			0,0	2			-				
-	\vdash	\vdash	-	-3	24	-	O.S.	, ,	-		-	 	-	-	ļ
	<u>.</u>	ļ				•	-	_		-			 		-
					<u>. </u>		-	¥					<u>.</u>		
								٠.						,	
		1						<u></u>							·
<u> </u>	-			├-		 	-	<u> </u>	-	 	<u> </u>	l	-	 	
	· <u>;</u>	ļ					<u> </u>	<u> </u>				<u> </u>			<u> </u>
••		<u> </u> -		Ŀ			L								L.
		24		·	ĺ										ļ
				<u> </u>			T -					-			
		<u> </u>	-	-				<u> </u>				-			-
		<u> </u>		<u> </u>				 		<u> </u>	-	<u> </u>	<u> -</u> _	 —	<u> </u>
			-				L			L_			_		
		-			Ì										
	<u> </u>	1	5												
			ا		4	-	-		 		 		┞─		-
·	<u> </u>	<u> </u>			ļ.,		<u> </u>		<u> </u>	<u> </u>	ļ				<u> </u>
				<u> </u>				<u> </u>							Ŀ
•]				ļ.					١.		
		1.	<u> </u>			· ·									
		-	<u> </u>	-				-			-	-	-	 	
			4	<u> </u>	•	<u> </u>		<u> </u>	ļ	<u> </u>	<u> </u>	<u> </u>		<u>:</u>	ļ
							<u>.</u>	<u> </u>	<u></u>					Ĺ	<u> </u>
-		Γ				1	1		_	1	_	1]	1	ļ . ¯

27`

Location	Date
Project / Client	




Location	Date
Project / Client	

_		Γ	Γ	1.	Ι					,	Γ			1 1	
	11-		pod	WB		الملكا	٦.	CL	PORC	48	AOV		- 5	18	<u> </u>
ļ ·	٠,	٠,٠	MIG	ii.	r+3	PIPE	,			! 					
	Ŀ		Į.						2 4	7 5				0)	LAT
0		COL	9711	100	ρ_	A.G×	<u>0 %</u>	120	Ch.A		(0)	3 (1.64	1	1010
		2	+ 1	w	0	ROCI	5.1	7	אע	.6T	<u> </u>				<u> </u>
ا ن	CZ	- 6	H =	3	g]		 							
			1		-										
├─	·			-	-								 		-
<u></u>					L	·					·				
									'	١.					
											<u> </u>				
-	_							 	_					-	-
		·						<u> </u>				.			<u> -</u>
i								.		ł					
		_							-		_				
			•					ļ				· ·	-		
														Ĺ	·
														 -	
												ļ			
							·								<u> </u>
														-~	
				-		-				-					
														<u> </u>	
								· 							Ŀ
						<u> </u>									<u> </u>
								-							_
														-	
						l :		L				L		<u>.</u>	


APPENDIX 3

UPDATED PIEZOMETER DATA AND GRAPHS


Inflows vs. Outflows June 23, 2011 to September 25, 2011




Inflow Volume vs. Outflow Volume June 23, 2011 to August 25, 2011



Piezometer P2 May 25, 2011 to September 29, 2011



Reservoir vs. P2
May 25th to September 29th 2011



P2 Reservoir

Gage Heights

OT= Over Topping

	W1234	W5 (GH,	D6 (GH below	W78 (GH,		W12 (GH,	URC02	LRC06	LRC01	LRC02	CC02	Reservoir
Date	(GH, ft)	ft)	top, ft.)	ft.)	ft.)	ft)	(GH, ft.)	(GH, ft)	(GH, ft)	(GH, ft)	(GH, ft.)	(GH)
9/25/2007	0.036	0.089				0.161			0.75			
9/26/2007	0.042	0.083				0.146						
11/9/2007	0.0417	0.063	0.938			0.146						
12/26/2007	0.0417	0.083	0.969			0.146						1
2/7/2008	0.0417	0.094	0.969			0.146						
3/10/2008	0.0417	0.042	0.901			0.177						
4/23/2008	0.1094	0.115	0.844			0.161			0.8			
5/16/2008	OT	0.104	0.615			0.344			1.15			
5/20/2008	OT		0.667			0.438						
6/3/2008	ОТ	0.208	0.698			0.427			1.24			
7/3/2008	0.1771	0.125	0.771			0.385			1.05			
8/8/2008	0.08	0.104	0.823			0.260						
10/2/2008	0.02	0.083	0.792			0.208			0.55			
12/1/2008	0.02	0.073	0.800			0.229						
12/12/2008	-		0.820							0.35	0.2	
1/15/2009	0.02	0.082	0.900			0.198	0.29			0.32	0.1	
2/20/2009	0.02	0.042	0.938			0.219	0.19		0.42		0.15	
4/7/2009			0.860					0.74		0.68	0.43	
4/13/2009	0.13	0.083	0.813			0.344		0.85		0.65	0.43	
4/24/2009	0.36		0.771	- · ·		0.406		1.33		1.41		2.15
4/30/2009	ОТ	0.208	0.750			0.417	1.14	1.265		1.302	0.55	
5/1/2009	0.83	0.188	0.760		0.55	0.427	1.11	1.21				1.95
5/5/2009	0.80	0.167	0.745	0.168	0.522	0.417		1.25		1.28	0.475	
5/7/2009								1.37		1.38	0.52	
5/19/2009	0.85			0.18	0.57		1.47			1.36	0.463	
5/27/2009	0.85	0.188		0.18	0.57	0.458	1.305		0.97			2.11
6/26/2009	0.478	0.146	0.854	0.125	0.51	0.396	0.61	0.77	0.79	0.769	0.18	
6/29/2009							0.565				 	1.18
7/24/2009	0.250	0.104		0.11	0.46	0.292	0.375	0.52	0.75	0.51	0.135	
8/21/2009	0.12		0.917	0.04	0.44		0.32	0.425	0.68		0.131	
9/11/2009	0.115	0.104	0.979	0.120			0.190	0.38	0.640		0.14	
10/23/2009		0.083	0.927	0.120			0.160			0.29	0.14	
11/25/2009	0.100	0.083	0.990	0.130			0.320			0.35	0.19	
12/29/2009	0.120	0.063	0.969				0.315		0.590			0.13

0.15	0.21	0.37	0.620	0.46	0.310	0.188	0.320	0.130	0.969	0.052	0.120	1/29/2010
0.16	0.24	0.40	0.650		0.340	0.198	0.320	0.120	0.990	0.042	0.130	3/3/2010
0.325	0.27	0.465			0.468	0.210	0.320	0.110	0.953	0.073	0.130	3/26/2010
0.92	0.277	0.547	0.710	0.585	0.591	0.210	0.380	0.130	0.886	0.083	0.240	4/30/2010
0.90	0.275	0.55	0.710		0.520	0.281		0.120	0.922	0.073	0.210	6/3/2010
1.55	0.297	0.597		0.062	0.848	0.333		0.100	0.885		0.28	6/25/2010
0.55	0.136	0.425	0.68		0.33	0.281		0.100	0.896	0.073	0.21	8/2/2010
0.130	0.126	0.339	0.640	0.375	0.240	0.210		0.100	0.948	0.040	0.16	8/23/2010
0.020	0.170	0.310	0.660	0.380	0.305	0.210		0.130	0.937	0.031	0.14	9/28/2010
		·	0.670	0.440	0.320	0.208		0.120	0.979	0.010	0.12	11/30/2010
-0.400	0.310	0.400	0.700	0.510	0.350	0.167		0.130	0.958	0.010	0.12	1/7/2011
		0.450	0.200		0.380	0.208		0.120	0.916	0.040	0.14	2/4/2011
-0.030	0.380	0.460	0.210	0.510	0.380	0.193		0.140	0.938	0.020	0.14	3/4/2011
0.450	0.490	0.730	0.280	0.800	0.720	0.323		0.130	0.875	0.063	0.24	3/31/2011
2.890	0.770	1.980	0.580	1.770	1.690	0.531		0.200	0.708	0.167	0.89	5/4/2011
3.330	1.020	OT	0.660	ОТ	2.540	0.583		0.200	0.688	0.218	0.98	5/18/2011
3.210	0.730	1.520	0.660	1.630	1.720	0.563		0.210	0.688	0.239	0.98	5/25/2011
2.750	0.430	1.690	0.640	1.700	1.320	0.531		0.200	0.688	0.292	0.94	6/23/2011
2.240	0.220		0.390	0.900	0.760	0.395		0.130	0.802	0.187	0.51	7/29/2011
1.370	0.140		0.300	0.650	0.490	0.333	<u></u>	0.100	0.849	0.146	0.25	8/25/2011
0.770	0.150		0.220	0.550	0.380	0.260		0.110	0.948	0.125	0.15	9/29/2011

	Р	A8	P2	PM1	PM2	P1	P3	P4	P5	PM3	PM4	PM5	PM6
Date	ft	ft	ft	ft	ft	ft	ft	ft	ft	ft	ft	ft	ft
4/24/2008	100.5	7.60	114.42	50.16	101.1	103.39	60.65	106.24	104.35	51.78	41.12	50.2	66.82
5/30/2008		2.71		48.2	88				:				
6/30/2008		2.93		48.36	90.71					_			
7/3/2008	100.34	4.65	105.4	49.73	97.49	101.9	dry	102.48	104.28	51.59	dry	dry	dry
8/8/2008	dry	6.97	117.8	53.12	101.1	dry	dry	dry	104.34	51.79	dry	dry	dry
10/1/2008		8.09		53.94									
1/15/2009	100.7	8.30	120.4	53.86	104.11	103.7	60.5	106.21	104.36	51.78	41.13	49.98	66.71
2/20/2009		8.20	119.9	53.69	103.75								
4/13/2009	101.55	6.88	112.87	51.43	100.24	103.8	60.4	106.05	103.44	51.78	41.1	50	66.8
4/24/2009	dry	4.59	98.18	45.37	92.13	103.68	dry	97.45	102.82	49.63	dry	dry	dry
4/30/2009	dry	3.48	91.55	44.66	87.81	dry	dry	91.28	99.09	49.69	dry	dry	dry
5/1/2009		3.44	91.45										
5/5/2009	dry	3.41	91.68	45.71	88.15	101.58	dry	98.97	98.71	_dry	dry	50.8	
5/27/2009	dry	2.65	90.4	45.62	89.6	96.88	dry	88.25	97.97	50.12	41.51	dry	dry
6/26/2009	dry	4.57	105.24	50.6	97.24	102.39	dry	102.21	104.25	50.02	dry	51.57	dry
6/29/2009		4.75	106.36										
7/24/2009	dry	6.42	114.13	52.07	100.41	dry	dry	dry	dry	50.02	dry	dry	dry
8/21/2009	dry	7.66	118.67	53.42	102.18	dry	dry	106.2	dry	dry	dry	50.04	dry
9/11/2009	dry	8.20	119.91	53.69	103.39	dry	dry	dry	dry	dry	dry	dry	dry
10/23/2009	dry	8.30	120.85	53.81	104.22	dry_	dry	dry	dry	dry	dry	dry	dry
11/25/2009	dry	8.31	120.56	63.71	104.25	dry_	dry	dry	dry	dry	dry	dry	dry
12/29/2009	dry	8.37	120.64	53.74	104.28	dry_	dry	dry	dry	dry	dry	dry	dry
1/29/2010	dry	8.32	120.24	53.65	dry	dry	dry	dry			dry	dry	dry
3/3/2010	dry	7.37	116.42	52.25	102.02	dry	dry	dry	dry	dry	dry	dry	dry
3/26/2010	dry	8.19	114.49	53.39	103.62	dry	dry	dry	dry	dry	dry	dry	dry
6/3/2010	dry	7.40	117.15	52.44	102.27	dry	dry	dry	dry	dry	dry	dry	dry
6/25/2010	dry	6.75	113.52	51.41	100.67	dry	dry	dry	104.09	51.52	dry	dry	dry
8/2/2010	dry	6.96	117.35	52.15	102.3	dry	dry	dry	dry	51.76	dry	dry	dry
9/28/2010	dry	8.34		53.15	104.4	dry	dry	dry	dry	dry	dry	dry	dry
10/29/2010	dry	8.30	120.68	52.92	104.43	dry	dry	dry	dry	dry	dry	dry	dry
11/30/2010	dry	8.26	120.25	52.5	104.25	dry	dry	dry	dry	dry	dгу	50.07	dry
1/7/2011	dry	8.15	119.75	51.95	103.85	dry	dry	dry	dry	dry	dry	50.07	dry
2/4/2011	dry	7.21	118.64	51.61	103.16	dry	dry	dry	dry	dry	dry	50.06	dry
3/4/2011	dry	7.48	118.1	51.58	102.3	dry	dry	dry	dry	dry	dry	51	dry

3/31/2011	dry	6.37	115.25	51.36	101.53	103.67	dry	dry	103.54	51.78	dry	50.06	dry
5/4/2011	dry	2.40	84.02	38.2	81.96	98.58	60.5	85.84	96.4	47.98	41.16	50.06	66.84
5/18/2011	dry	1.40	72.25	34.42	75.14	90.16	dry	71.97	94.14	46.3	40.14	50,06	dry
5/25/2011	dry	1.30	72.98	33.88	74.51	89.27	dry	70.58	93.9	46.03	40.32	50.07	dry
6/23/2011	dry	1.30	78.73	35.53	82.62	88.22	dry	75.04	94.18	46.85	41.12	dry	dry
7/29/2011	dry	4.10	105.09	50.73	94.01	100.23	dry	101.6	103.99	51.32	41	50.1	dry
8/25/2011	dry	5.27	113.29	53.14	98.89	dry	dry	106.21	104.28	51.57	41.17	50.07	dry
9/29/2011	dry	6.93	118.29	53.93	102.28	dry	dry	106.21	104.28	51.76	dry	50.07	dry

From

S:\DOCUMENT\JOB FILES\Jobs\R\R_56_01\Documents\Annual Inspection\PIEZOMETERS

Billmayer & Hafferman Inc.

Kootenai Development Impoundment Dam Annual Inspection

3-Nov-10 Last Update

Haffeman

Bold = interpolated values

Wet Piezometer Plots

Piezometer Num	P2		Elev.	PM1		Elev.	PM2		Elev.	A8		Elev.
		T.O.C.=	2920.54		T.O.C.=	2846.41		T.O.C.=	2903.34		T.O.C.=	2795.11
,												
Date	DW	TD	WS Elev	DW	TD	WS Elev	DW	TD	WS Elev	DW	TD	WS Elev
9/29/2011	118.29	122.23	2802.25	53.93	54.92	2792.48	102.28	104.88	2801.06	6.93	28.23	2788.18
8/25/2011	113.29	122.23	2807.25	63.14	54.92	2793.27	98.89	104.88	2804.45	5.27	28.23	2789.84
7/29/2011	105.09	122.28	2815.45	50.73	54.91	2795.68	94.01	104.96	2809.33	4.1	28.26	2791.01
6/23/2011	78.73	122.28	2841.81	35.53	54.91	2810.88	82.62	104.96	2820.72	1.3	28.26	2793.81
5/25/2011	72.98	122.28	2847.66	33.88	54.91	2812.53	74.51	104.96	2828.83	1.3	28.26	2793.81
5/18/2011	72.25	122.28	2848.29	34.42	54.87	2811.99	75.14	104.92	2828.2	1.4	28.24	2793.71
5/4/2011	84.02	122.28	2836.52		54.82	2808.21	81.96	104.57	2821.38	2.4	28.25	2792.71
3/31/2011	115.25	122.27	2805.29	51.36	54.83	2795.05	101.53	104.85	2801.81	6.37	28.24	2788.74
3/4/2011	118.1		2802.44	51.58		2794.83	102.3		2801.04	7.48		2787.63
2/4/2011	118.64	122.24		51.61	54.82	2794.8	103.16	104.77	2800.18	7.21	28.21	2787.90
1/7/2011	119.75	122	2800.79		54.85	2794.46	103.85	104.8	2799.49	8.15	28.2	2786.96
11/30/2010	120.25	122.3	2800.29	52.5	54.85	2793.91	104.25	104.8	2799.09	8.26	28.2	2786.85
10/29/2010	120.68	122	2799.86	52.92	54.85	2793.49	104.43	104.95	2798.91	8.3	28.2	2786.81
9/28/2010	122.6	122.1	2797.94	53.15	54.8	2793.26	104.4	104.6	2798.94	8.34	28.3	2786.77
8/2/2010	117.35	122.1	2803.19	52.15	54.8	2794.26	102.3	104.6	2801.04	6.96	28.3	2788.15
6/25/2010	113.52	122.1	2807.02	51.41	54.8	2795	100.67	104.6	2802.67	6.75	28.3	2788.36
6/3/2010	117.5	122.1	2803.04	52.44	54.8	2793.97	102.27	104.6	2801.07	7.4	28.3	2787.71
3/26/2010	114.49	122.1	2806.05	53.39	54.8	2793.02	103.62	104.6	2799.72	8.19	28.3	2786.92
3/3/2010	116.42	122.1	2804.12	52.25	54.8	2794.16	102.2	104.6	2801.14	7.37	28.3	2787.74
1/29/2010	120.24	122.1	2800.3	53.65	54.8	2792.76	104.6	104.6	2798.74	8.32	28.3	2786.79
12/29/2009	120.64	122.1	2799.9	53.74	54.8	2792.67	104.28	104.6	2799.06	8.37	28.3	2786.74
11/25/2009	120.56	122.1	2799.98	53.71	54.8	2792.7	104.25	104.6	2799.09	8.31	28.3	2786.80
10/23/2009	120.86	122.1	2799.69	53.81	54.8	2792.6	104.22	104.6	2799.12	8.3	28.3	2786.81


Piezometer Num	P2		Elev.	PM1		Elev.	PM2		Elev.	A8		Elev.
		T.O.C.=	2920.54		T.O.C.≂	2846.41		T.O.C.=	2903.34		T.O.C.=	2795.11
Date	DW	TD	WS Elev	DW	TD	WS Elev	DW	TD	WS Elev	DW	TD	WS Elev
9/11/2009	119.91	122.1	2800.63	53.69		2792.72	103.39	104.6	2799.95	8.2	28.3	2786.91
8/21/2009	118.67	122.1	2801.87	53.42	54.8	2792.99	102.18	104.6	2801.16	7.66	28.3	2787.45
7/24/2009	114.13	122.1	2806.41	52.07	54.8	2794.34	100.41	104.6	2802.93	6.42	28.3	2788.69
6/29/2009	106.36	122.1	2814.18	50.73	54.8	2795.68	97.52	104.6	2805.82	4.75	28.3	2790.36
6/26/2009	105.24	122.1	2815.3	50.6	54.8	2795.81	97.24	104.6	2806.1	4.565	28.3	2790.55
5/27/2009	90.4	122.1	2830.14	45.62	54.8	2800.79	89.6	104.6	2813.74	2.65	28.3	2792.46
5/5/2009	91.68	122.1	2828.86	45.71	54.8	2800.7	88.15	104.6	2815.19	3.41	28.3	2791.70
5/1/2009	91.45	122.1	2829.09	44.56	54.8	2801.85	87.52	104.6	2815.82	3.44	28.3	2791.67
4/30/2009	91.55	122.1	2828.99	44.66	54.8	2801.76	87.81	104.6	2815.53	3.48	28.3	2791.63
4/24/2009	98.18	122.1	2822.36	45.37	54.8	2801.04	92.13	104.6	2811.21	4.59	28.3	2790.52
4/13/2009	112.87	122.1	2807.67	51.43	54.8	2794.98	100.24	104.6	2803.1	6.88	28.3	2788.23
2/20/2009	119.9	122.1	2800.64	53.69	54.8	2792.72	103.75	104.6	2799.59	8.2	28.3	2786.91
1/15/2009	120.4	122.1	2800.14	53.86	54.8	2792.55	104.11	104.6	2799.23	8.3	28.3	2786.81
12/1/2008	120.61	122.1	2799.93	53.9	54.8	2792.51	104.07	104.6	2799.27	8.21	28.3	2786.90
10/30/2008	119.17	122.1	2801.37	53.87	54.8	2792.54	103.91	104.6	2799.43	8.18	28.3	2786.93
10/2/2008	117.9	122.1	2802.64	53.94	54.8	2792.47	104.6	104.6	2798.74	8.09	28.3	2787.02
8/8/2008	115.78	122.1	2804.76	53.12	54.8	2793.29	101.1	104.6	2802.24	6.97	28.3	2788.14
7/3/2008	105.4	122.1	2815.14	49.73	54.8	2796.68	97.49	104.6	2805.85	4.65	28.3	2790.46
6/3/2008	87.52	122.1	2833.02	48.36	54.8	2798.06	90.71	104.6	2812.63	2.93	28.3	2792.18
5/20/2008	90.49	122.1	2830.05	48.17	54.8	2798.24	88	104.6	2815.34	2.67	28.3	2792.44
5/16/2008	91.34	122.1	2829.2	46.45	54.8	2799.96	88.4	104.6	2814.94	3.88	28.3	2791.23
4/23/2008	114.42	122.1	2806.12	50.16	54.8	2796.25	101.1	104.6	2802.24	7.6	28.3	2787.51
3/10/2008	119.65	122.1	2800.89	51.47	54.8	2794.94	103.53	104.6	2799.81	8.4	28.3	2786.71
2/7/2008	120.1	122.1	2800.44	51.2	54.8	2795.21	103.8	104.6	2799.54	8.55	28.3	2786.56
12/26/2007	120.34	122.1	2800.2	51.52	54.8	2794.89	103.98	104.6	2799.36	8.52	28.3	2786.59
11/9/2007	121.3	122.1	2799.24	51.65	54.8	2794.76	104	104.6	2799.34	8.75	28.3	2786.36
9/27/2007	119.12	122.1	2801.42	51.75	54.8	2794.66	103.12	104.6	2800.22	7.22	28.3	2787.89
5/8/2007	107.64	122.1	2812.9	49.57	54.8	2796.84	96.18	104.6	2807.16	5.22	28.3	2789.89
11/14/2006	119.21	122.1	2801.33	51.88	54.8	2794.53	102.72	104.6	2800.62	7.96	28.3	2787.15
10/30/2006	119.48	122.1	2801.06	51.82	54.8	2794.59	103.69	104.6	2799.65	7.92	28.3	2787.19

Piezometer Num	P2		Elev.	PM1		Elev.	PM2	- 	Elev.	A8		Elev.
		T.O.C.=	2920.54		T.O.C.=	2846.41		T.O.C.=	2903.34		T.O.C.=	2795.11
		TD	WS Elev	DW	TD	WS Elev	DW	TD	WS Elev		TD	WS Elev
8/16/2006	119.39	122.1	2801.15	51.72	54.8	2794.69		104.6	2799.83	7.72	28.3	
7/28/2006	119.14	122.1	2801.4	51.61	54.8	2794.8	103.32	104.6	2800.02	7.42	28.3	
6/21/2006	110.89	122.1	2809.65	51.23	54.8	2795.18		104.6	2801.72	6.18	28.3	
5/27/2006	109.78	122.1	2810.76	50.76	54.8	2795.65	98.92	104.6	2804.42	4.98	28.3	2790.13
4/7/2006	114.34	122.1	2806.2	51.14	54.8	2795.27	99.79	104.6	2803.55	4.96	28.3	2790.15
3/12/2006	119.52	122.1	2801.02	51.62	54.8	2794.79	103.39	104.6	2799.95	6.18	28.3	2788.93
2/24/2006	119.44	122.1	2801.1	51.95	54.8	2794.46	103.79	104.6	2799.55	7.92	28.3	2787.19
10/27/2005	119.41	122.1	2801.13	51.94	54.8	2794.47	103.76	104.6	2799.58	7.81	28.3	2787.30
9/10/2005	119.32	122.1	2801.22	51.84	54.8	2794.57	103.66	104.6	2799.68	7.76	28.3	2787.35
8/27/2005	119.3	122.1	2801.24	51.78	54.8	2794.63	103.14	104.6	2800.2	7.68	28.3	2787.43
7/14/2005	119.22	122.1	2801.32	51.74	54.8	2794.67	103.46	104.6	2799.88	7.28	28.3	2787.83
6/24/2005	112.79	122.1	2807.75	51.68	54.8	2794.73	103.29	104.6	2800.05	6.22	28.3	2788.89
5/29/2005	119.42	122.1	2801.12	50.92	54.8	2795.49	103.01	104.6	2800.33	5.91	28.3	2789.20
4/10/2005	119.7	122.1	2800.84	51.72	54.8	2794.69	103.32	104.6	2800.02	5.42	28.3	2789.69
3/19/2005	119.82	122.1	2800.72	51.82	54.8	2794.59	103.49	104.6	2799.85	7.79	28.3	2787.32
2/13/2005	119.86	122.1	2800.68	51.87	54.8	2794.54	103.54	104.6	2799.8	7.86	28.3	2787.25
11/19/2004	119.9	122.1	2800.64	51.91	54.8	2794.5	103.59	104.6	2799.75	7.96	28.3	2787.15
10/17/2004	119.89	122.1	2800.65	51.84	54.8	2794.57	103.52	104.6	2799.82	7.91	28.3	2787.20
9/24/2004	119.91	122.1	2800.63	51.81	54.8	2794.6	103.49	104.6	2799.85	7.82	28.3	2787.29
8/17/2004	119.84	122.1	2800.7	51.79	54.8	2794.62	103.34	104.6	2800	7.79	28.3	2787.32
7/22/2004	119.21	122.1	2801.33	51.72	54.8	2794.69	103.29	104.6	2800.05	7.42	28.3	2787.69
6/18/2004	116.8	122.1	2803.74	50.69	54.8	2795.72	102.14	104.6	2801.2	7.01	28.3	2788.10
5/25/2004	115.14	122.1	2805.4	50.95	54.8	2795.46	101.34	104.6	2802	6.55	28.3	2788.56
3/19/2004	119.74	122.1	2800.8	51.68	54.8	2794.73	101.46	104.6	2801.88	7.8	28.3	2787.31
2/12/2004	119.45	122.1	2801.09	51.82	54.8	2794.59	103.52	104.6	2799.82	7.8	28.3	2787.31
12/10/2003	119.44	122.1	2801.1	51.86	54.8	2794.55	103.54	104.6	2799.8	7.91	28.3	2787.20
11/19/2003	119.72	122.1	2800.82	51.84	54.8	2794.57	103.59	104.6	2799.75	7.9	28.3	2787.21
10/21/2003	119.32	122.1	2801.22	51.84	54.8	2794.57	103.54	104.6	2799.8	7.94	28.3	2787.17
9/23/2003	119.51	122.1	2801.03	51.76	54.8	2794.65	103.49	104.6	2799.85	7.7	28.3	2787.41
8/26/2003	119.42	122.1	2801.12	51.62	54.8	2794.79	103.42	104.6	2799.92	7.68	28.3	2787.43


Piezometer Num	P2		Elev.	PM1		Elev.	PM2		Elev.	A8		Elev.
		T.O.C.=	2920.54		T.O.C.=	2846.41		T.O.C.=	2903.34		T.O.C.=	2795.11
Date	DW	TD	WS Elev	DW	TD	WS Elev	DW	TD	WS Elev	DW	TD	WS Elev
7/29/2003	119.16	122.1	2801.38	51.58	54.8	2794.83	103.38	104.6	2799.96	7.39	28.3	2787.72
6/14/2003	101.34	122.1	2819.2	50.62	54.8	2795.79	101.23	104.6	2802.11	6.22	28.3	2788.89
5/30/2003	103.62	122.1	2816.92	49.67	54.8	2796.74	94.67	104.6	2808.67	4.62	28.3	2790.49
4/28/2003	112.74	122.1	2807.8	50.02	54.8	2796.39	97.48	104.6	2805.86	3.41	28.3	2791.70
3/28/2003	119.62	122.1	2800.92	51.99	54.8	2794.42	102.91	104.6	2800.43	6.21	28.3	2788.90
2/24/2003	119.82	122.1	2800.72	52.74	54.8	2793.67	103.9	104.6	2799.44	7.62	28.3	2787.49
12/18/2002	119.34	122.1	2801.2	51.74	54.8	2794.67	103.36	104.6	2799.98	7.77	28.3	2787.34
9/30/2002	119.28	122.1	2801.26	51.55	54.8	2794.86	103.12	104.6	2800.22	7.22	28.3	2787.89
7/31/2002	111.72	122.1	2808.82	50.54	54.8	2795.87	98.87	104.6	2804.47	5.46	28.3	2789.65
6/28/2002	91.22	122.1	2829.32	48.82	54.8	2797.59	89.63	104.6	2813.71	2.62	28.3	2792.49

.


KDID Piezometers 2009 to 2011 with Reservoir Gauge Height




KDID P2 and Base reservoir and Embankment Toe 2002 to 2011




KDID Piezometers July 1, 2002 to August 25, 2011




KDID All "Wet" Piezometer Elevations 2008 - 2011



KDID Piezometer A8 at the Toe of the Embankment



Upper Rainy Creek Inflow and Flume 1-4, Drain 6 and Drain 12 Flows 2009-2011



URC02 Inflows, Drain 6 Outflow and Piezometer P2

